

GREGORY S. BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed Y

A	Report D	oate: 07/14/201	.5		
Mine Name: Lost Sheep Mine		Permit Number:	S/023/0029	Mine Status:	Active
Operator Name: Michael Provstgaard		Inspection Date:	07/09/2015	Permit Fees:	Paid
Inspector(s): Wayne Western		Inspection Time:	10:30 -10;45	am Bond Amount:	\$11,400
Attendee(s):		Weather:	clear and war	rm Bond Escalation:	03/13/2015
Insp	ection Purpose: Routine inspection			Prior Inspection:	10/21/2014
	clusions and Recommendations Division sent a letter requesting additional bond. Produc	ction in 2014 was 20 to	ons of material s	shipped off site.	
Elements of Inspection			Evaluated & Commented	Enforcement	
1.	Permits, Revisions, Transfer, Bonds			\boxtimes	
	Permit fees for 2015 paid. Bond needs to be escalated	- letter sent.			
2.	Public Safety (shafts, adits, trash, signs, highwalls)				
	Vehicle access to the site is restricted by two locked ga	tes. There is little evid	dence of visits t	o the site by the public.	
3.	Protection of Drainages/Erosion Control				. 🗆
	Ditches control the drainage. No signs of erosion				
4.	Deleterious Material				
	All equipment at the site is stored properly.				
5.	Roads (maintenance, surfacing, dust control, safety)				
6.	Reclamation				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, sl	hafts)			
8.	Soils				
9.	Revegetation				
10.	Other				

Inspector's Signature: CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230029-LostSheep/inspections/Insp07092015.pdf



S/023/0029 Mine: Page 2 of 2


Inspected: 07/09/2015




Conex box and storage shed in good condition



Stockpiles on site



Conveyors on site - note the vegetation in the pad area.



Pad area looking west. No signs of recent activity.

